
ASSEMBLY INSTRUCTIONS




1. Remove the display from the transport bag.




2. Release Flex-o, the display will take shape on its own.



 ${\bf 3.}$ Spread the trestle parts and join the Velcro.



4. Use the supplied pegs to secure Flex-o to the ground.



The edging area is intended to be entirely covered. Then fill with just the base, without any important elements.

Bring the path to the indicated dimensions.



- ABUNDANCE

- CUT

- SAFETY MARGIN
(Do not place important content beyond this margin))

INFO FILE

Formats: .eps .pdf .jpg .tiff
Color profile: CMYK

Images: 100dpi - 1000dpi (for 1:10 scale files)

Fonts: converted into paths

Die path: only cutting path (where present)

